



EAGLE
Environmental, Inc.



Hazardous Building Materials > Industrial Hygiene/IAQ > Environmental Assessments > Laboratory Services & Training

July 24, 2014

Mr. David Holmes
Capital Studio Architects
1379 Main Street
East Hartford, CT 06108

RE: Environmental Assessment Report
Department of Housing
CDBG-DR – Sandy Disaster Recovery Program
2 Apple Tree Lane
West Mystic, Connecticut 06512
Application #2011
Eagle Project No. 14-028.12T17


Dear Mr. Holmes:

Please find the attached Environmental Assessment Report conducted at 2 Apple Tree Lane located in West Mystic, Connecticut (Site). The environmental assessment was performed in support of the planned renovations/repairs to the Site building under the State of Connecticut Department of Housing Community Development Block Grant – Disaster Recovery Program (Program). The assessment focused only on those areas of the building that are scheduled for renovation/repair work with the exception of the lead-based paint hazard screen, which included the interior and exterior of the entire building. The proposed scope of renovation/repair work was provided to Eagle Environmental, Inc. (Eagle) by Capital Studio Architects (CSA).

This assessment and report is intended to satisfy the review process of the National Environmental Policy Act (NEPA) Statutory Checklist Sections 13C (Lead-Based Paint), 13D (Asbestos), 13E (Radon) and 13F (Mold).

Please do not hesitate to contact us if you have any questions regarding the contents of this report.

Sincerely,
Eagle Environmental, Inc.


Report Prepared By:
Kristen Liljehult

Environmental Consultant II


Report Reviewed By:
Peter J. Folino
Project Manager

\\Eaglesvr\public\2014 Files\2014 Reports\Capital Studio Architects\Hurricane Sandy\2 Appletree Lane - West Mystic\2 Apple Tree Ln - HAZ
Inspection Report.doc

8 SOUTH MAIN STREET, SUITE 3 • TERRYVILLE, CT 06786
PHONE (860) 589-8257 • FAX (860) 585-7034

TABLE OF CONTENTS

1. INTRODUCTION.....	1
1.1 INSPECTION AREA DESCRIPTION	1
2. SCOPE OF INSPECTION.....	1
2.1 ASBESTOS CONTAINING MATERIALS	3
2.2 LEAD-BASED PAINT	3
2.3 RADON TESTING	3
2.4 MOLD INSPECTION	3
3. INSPECTION PROTOCOLS.....	3
3.1 ASBESTOS CONTAINING MATERIALS	3
3.1.1 Inspection	3
3.1.2 Bulk Sampling.....	4
3.1.3 Bulk Sample Analysis.....	4
3.2 LEAD-BASED PAINT	5
3.3 RADON TESTING	5
3.4 MOLD INSPECTION	5
4. INSPECTION RESULTS	6
4.1 ASBESTOS CONTAINING MATERIALS	6
4.2 LEAD-BASED PAINT	7
4.2.1 Dust Hazards	7
4.2.2 Soil Hazards	7
4.3 RADON.....	8
4.4 MOLD.....	8
5. COST ESTIMATES	8

LIST OF TABLES

Table I	Asbestos-Containing Materials Summary Table
Table II	Non Asbestos-Containing Materials Summary Table

APPENDICES

Appendix 1	Floor Plans
Appendix 2	Asbestos Bulk Sample Laboratory Reports
Appendix 3	Interior and Exterior Visual Assessment Forms
Appendix 4	XRF Lead-Based Paint Inspection Reports
Appendix 5	Lead Dust Sample Laboratory Reports
Appendix 6	Radon Testing Reports
Appendix 7	Mold Inspection Forms
Appendix 8	Abatement and Consulting Cost Estimates
Appendix 9	Eagle Environmental Inc. Licenses and Laboratory Certificates

1. INTRODUCTION

On July 10, 2014, Eagle Environmental, Inc. conducted an environmental assessment of portions of the site building located at 2 Apple Tree Lane in West Mystic, Connecticut. The scope of the environmental assessment included an inspection for asbestos-containing materials, a lead-based paint screen and a visual inspection for microbial contamination.

1.1 Inspection Area Description

The inspection area included those areas of the building that will be impacted by planned renovation work. The areas of inspection are determined by reviewing the planned renovation work provided in CSA's Project Scope dated May 19, 2014. For the purpose of this project the following areas were inspected:

- Basement
- Façade A

In addition to testing the areas of the building that will be impacted by the renovation work, a lead hazard screen was performed throughout the site building to comply with federal funding requirements for a residential building receiving Federal funding assistance under a Department of Housing and Urban Development (HUD) administered program.

A complete list of components that were tested may be found in the XRF Lead Inspection Detailed Report.

2. SCOPE OF INSPECTION

2.1 Asbestos Containing Materials

The asbestos inspection was conducted to identify and sample suspect asbestos-containing materials within the areas of proposed renovation or repair work. Although federal regulations requiring asbestos inspection do not pertain to a residential structure containing less than five (5) units, demolition or renovation activities which may disturb asbestos would be unauthorized under the State of Connecticut Department of Public Health (DPH) regulations. Disposal of asbestos containing waste in unauthorized landfills is also prohibited. The inspection was performed to facilitate compliance with these applicable abatement and disposal regulations.

The asbestos inspection was performed by Andrew Carnevale; a State of Connecticut licensed Asbestos Inspector (license #000850).

2.2 Lead-based Paint

A lead-based paint hazard screen was performed at the site building to comply with the Department of Housing and Urban Development (HUD) Lead Safe Housing Rule (24 CFR 35) for a residential property receiving Federal rehabilitation assistance under a program administered by HUD.

Certain lead-based paint requirements apply to each project depending on the level of Federal Funding allocated. The lead-based paint requirements include the following for each level of funding:

1. Residential property receiving \$5,000 or less per unit (Not Applicable to this Project):
 - a. Conduct lead-based paint testing or presume all painted surfaces contain toxic levels of lead-based paint. If lead-based paint testing confirms that the painted surfaces are not coated with lead-based paint, lead safe work practices and clearances are not required.
 - b. Conduct a risk assessment in each unit receiving Federal funds. ~~in~~ common areas and the exteriors.
 - c. Interim control measures may be utilized throughout the building
 - d. Lead safe work practices are to be utilized during rehabilitation work that will disturb painted surfaces.
 - e. After the completion of any rehabilitation work that has disturbed painted surfaces, clearances are to be performed.

2. Residential property receiving between \$5,000 and \$25,000 per unit:
 - a. Conduct lead-based paint testing or presume all painted surfaces contain toxic levels of lead-based paint. If lead-based paint testing confirms that the painted surfaces are not coated with lead-based paint, lead safe work practices and clearances are not required.
 - b. Lead safe work practices are to be utilized during rehabilitation work that will disturb lead-based painted surfaces.
 - c. Perform interim controls on all lead hazards identified during the lead hazard screen.
 - d. Perform clearance testing following interim control work and renovations.
 - e. Provide notice of lead-hazard reduction within 15 days of completion of work.

3. Residential property receiving greater than \$25,000 per unit:
 - a. **Conduct lead-based paint testing or presume all painted surfaces contain toxic levels of lead-based paint. If lead-based paint testing confirms that the painted surfaces are not coated with lead-based paint, lead safe work practices and clearances are not required.**
 - b. **Conduct a risk assessment in each unit receiving Federal funds, in common areas and the exteriors.**
 - c. **Abate all interior lead-based paint hazards identified during the lead inspection/risk assessment. Interim controls are acceptable on exterior surfaces that are not disturbed by rehabilitation and on paint-lead hazards that are below the de minimus levels.**
 - d. **Lead safe work practices are to be utilized during rehabilitation work that will disturb painted surfaces.**
 - e. **Perform clearance testing following abatement work.**

f. Provide notice of lead-hazard reduction within 15 days of completion of work.

The lead-based paint hazard screen was performed by Kristen Liljehult; a State of Connecticut licensed Lead Inspector/Risk Assessor (license # 002206).

In addition to HUD's Lead Safe Housing Rule, the State of Connecticut Department of Public Health Lead Poisoning Prevention and Control regulations apply when a child under the age of six (6) years old lives in the residence at the time of the inspection. The lead hazard screen was performed in accordance with State requirements, where applicable. There were no children under six (6) years of age residing in the dwelling at the time of inspection.

2.3 Radon Testing

Radon testing for this program is performed on a case-by-case basis. Building's which are constructed on piers with its lowest level not in contact with the ground are not considered for Radon testing.

Buildings, which are not elevated off the ground are tested for Radon under this Program. Radon testing is performed to comply with the National Environmental Policy Act (NEPA).

At a minimum, the Indoor Radon Potential Map of Connecticut was reviewed to determine each sites geographic location in respect to indoor Radon potential.

2.4 Mold Inspection

Eagle performed a visual inspection for the presence of suspect mold within the inspection areas. The inspection included an investigation for signs of visible microbial growth including discoloring of building materials, mal odors and water intrusion that may inhibit microbial growth. The inspection was visual in nature and did not include any sampling or destructive investigations behind rigid walls or ceilings.

3. INSPECTION PROTOCOLS

3.1 Asbestos Containing Materials

3.1.1 Inspection

The asbestos-containing materials (ACM) inspection included the accessible interior and exterior portions of the building that will potentially be impacted by the proposed renovation/repair work. The inspection did not include areas outside of the proposed renovation/repair work areas.

Semi-destructive testing techniques were utilized during the inspection process. This included removing small pieces of suspect materials for analysis (bulk sampling). Only those building materials that will be impacted by the proposed renovation/repair work were sampled. Wood, glass, metal and fiberglass are not defined as suspect materials and are not sampled.

During the inspection, suspect materials are located, sampled, quantified and the friability of the material is determined. Friable materials are those materials that hand pressure can crumble, pulverize or reduce to powder when dry.

An estimated quantity of identified ACM is provided for positive materials only. The materials are quantified in linear or square feet, depending on the nature of the material.

3.1.2 Bulk Sampling

During the sampling process, suspect ACM is separated into three (3) USEPA categories. These categories are: Thermal System Insulation (TSI), Surfacing Materials (SURF), and Miscellaneous materials (MISC). TSI includes all materials used to prevent heat loss or gain or water condensation on mechanical systems. Examples of TSI are pipe covering, boiler insulation, duct wrap, and mudpack fitting cement. Surfacing ACM includes all ACM that is sprayed, towed or otherwise applied to an existing surface. These applications are most commonly used in fireproofing, decorative, and acoustical applications. Miscellaneous materials include all ACM not listed in thermal or surfacing, such as linoleum, vinyl asbestos flooring, and ceiling tile.

Bulk sampling was performed in a random method. Bulk sampling methods and number of samples collected meets or exceeds the USEPA requirements.

3.1.3 Bulk Sample Analysis

The samples of the suspect asbestos containing materials were sent to a State of Connecticut Department of Public Health (DPH) approved laboratory for analysis by Polarized Light Microscopy (PLM). PLM is the USEPA accepted method of analysis for identification of asbestos in bulk matrixes. Samples are collected individually or in sets. When sets of samples are collected, each set is systematically analyzed until one sample is determined to contain asbestos. Upon the determination of the presence of asbestos in one sample in the set, analysis of the remaining samples in the set is discontinued. If no asbestos is observed during analysis of the set of samples, the suspect material is determined to be negative for asbestos content.

Sample analysis results are reported in percentage of asbestos and non-asbestos components. The USEPA defines any material that contains greater than one percent asbestos, utilizing PLM, as being an asbestos-containing material (ACM). Suspect materials containing greater than one percent (1%) asbestos utilizing the PLM Point Count Method and the NOB TEM method are also considered to be asbestos-containing. Materials determined to contain greater than one percent (1%) asbestos is regulated by the USEPA, the State of Connecticut Department of Public Health and Department of Energy and Environmental Protection and the United States Department of Labor. Sample results indicating "no asbestos detected" (NAD) are specified as non-asbestos containing materials. Samples results indicating "Did Not Analyze" (DNA) are not analyzed due to the stop on first positive request to the laboratory.

3.1.3.1 Friable ACM Analysis

Certain samples of friable materials shown to contain less than 10% asbestos are analyzed further by the "Point Count Method". This procedure is recommended by the United States Environmental Protection Agency to confirm friable bulk samples shown to have less than 10% asbestos by PLM to be definitively negative or positive for asbestos. This method is accepted as providing statistically reliable results when analyzing bulk samples with very low asbestos concentrations. Friable materials containing "Trace" or "less than one percent (1%)" asbestos must be analyzed by the PLM Point Count Method. No samples were further analyzed by the PLM Point Count Method for the 2 Apple Tree Lane in West Mystic, Connecticut.

3.1.3.2 Non Friable ACM Analysis

Certain samples of organically bound non-friable materials shown to contain "less than 1% asbestos", "TRACE" or "NAD" are recommended for analyses by the "NOB TEM ELAP 198.4 Method". This procedure is recommended by the United States Environmental Protection Agency to further evaluate non-friable organically bound materials for asbestos. Suspect materials confirmed by NOB TEM to be "less than 1% asbestos", "TRACE" or "NAD" are considered non-asbestos containing. No samples were further analyzed by the NOB TEM Method for the 2 Apple Tree Lane in West Mystic, Connecticut.

3.2 Lead-based Paint

The lead hazard screen was performed utilizing an X-Ray Fluorescence (XRF) Radiation Monitoring Device (RMD) Lead Paint Analyzer (LPA 1), serial number 2753 throughout the building.

Due to the level of proposed Federal Funding for this project (exceeding \$25,000 per unit), the lead-based paint screen included testing surfaces where defective paint or surface coatings were identified. A visual inspection was performed to evaluate the condition of surface coating associated with the building. Where surface coatings were defective (peeling, chipping, flaking, etc.), paint testing was performed. Component and surface locations are identified by side designations represented by the letters "A", "B", "C", and "D". The "A" side is considered the front of the building with the "B", "C", and "D" sides following in a clockwise order.

The data is presented on computer generated Lead Inspection Reports contained in Appendix 3. The Summary Report provides an inventory of each surface coating that contains lead at or above 1.0 mg/cm². The Detailed Report is an inventory of each tested surface on a room-by-room basis.

For the purpose of this report, lead-based paint is defined as surface coatings that contain ≥ 1.0 mg/cm² of lead by XRF.

In addition to XRF testing, dust samples are collected at the time of inspection if defective lead-based paint is identified. The exterior grounds are evaluated as well and if bare areas of soil are identified, soil samples are collected. Any dust or soil hazards identified are incorporated into the Lead-Based Paint Hazard Reduction or Abatement Plan.

3.3 Radon Testing

The site building is planned to be raised to proper flood elevation and the lowest level of the building will not be in contact with the ground. Radon testing was not performed for this site building.

3.4 Mold Inspection

Eagle Environmental, Inc. performed a visual inspection within the limits of the inspection area for potential microbial growth. The visual inspection was performed to evaluate building materials for signs of water damage and suspect microbial growth. Building materials such as gypsum board, cellulose ceiling tiles, paper pipe coverings or duct coverings and heating, ventilation and air conditioning components were visually assessed. Only visible accessible materials were inspected within the proposed areas of renovation/repair.

Discoloration and decay of the aforementioned building materials may signify mold growth. Water damage or damp conditions may also signify suitable conditions for mold growth.

Suspect mold growth or conditions that may sustain mold growth were documented during the inspection process. In general, the location, color of suspect growth and estimated quantity of impacted building materials were recorded during the inspection process.

Eagle used an Extech Instruments Model MO290 Moisture/Humidity Meter to measure the relative moisture content of accessible representative building materials that may have been impacted by water during the storm. A "dry standard" for each component was determined by averaging the moisture measurements for materials in un-impacted areas. The "dry standard" was used as a baseline comparison to determine if the materials were wet. Moisture measurements were recorded on the Mold Moisture Reading Form.

4. INSPECTION RESULTS

4.1 Asbestos Containing Materials

During the course of the building inspection twenty-eight (28) bulk samples of suspect ACM were collected and twenty-six (26) samples were analyzed by PLM based on the "stop on first positive" request to the laboratory.

The following materials were confirmed to be ACM:

- Breeching insulation in Room 001 (Laundry Room)

The summaries of asbestos and non-asbestos materials are presented in Tables I and II respectively. The asbestos analysis laboratory reports are provided in Appendix 2.

A licensed Asbestos Abatement Contractor shall remove the breeching insulation prior to the basement being filled in. The Asbestos Abatement Contractor will comply with the US Department of Labor's Occupational Safety and Health Administration (OSHA), the USEPA National Emission Standard for Hazardous Air Pollutants, the CT DEEP regulated waste disposal regulations and the State of Connecticut Standard for Asbestos Abatement.

Any suspect material not specifically identified in this report as non-ACM should be assumed to contain asbestos unless sample results prove otherwise.

All regulated friable and regulated non-friable ACM must be removed prior to renovation/repair activities. A State of Connecticut Licensed Asbestos Abatement Contractor must be retained to perform the removal work. Visual inspections and air clearances must be performed within each abatement area at the completion of the abatement work. The visual inspections and air clearances must be performed by a State of Connecticut licensed Asbestos Project Monitor. The abatement areas must meet final visual and air clearance inspection criteria prior to building renovation / demolition. Re-occupancy air monitoring is required if the building will be re-entered by any person following abatement and prior to demolition. This includes but is not limited to entry for utility disconnects, salvage, equipment removal, etc.

The Asbestos Abatement Contractor must submit a notice of asbestos abatement to the State of Connecticut Department of Public Health post marked or hand delivered ten (10) days prior to the commencement of any asbestos abatement activities involving the

abatement of greater than ten (10) linear feet or twenty-five (25) square feet of asbestos-containing materials. The asbestos abatement notification satisfies the DPH regulatory requirements for demolition notification. For asbestos abatement projects involving less than ten (10) linear feet or twenty-five (25) square feet of asbestos-containing materials or projects where no regulated asbestos-containing materials are identified, the facility owner or any person who will be conducting demolition must submit a demolition notification to the State of Connecticut Department of Public Health post marked or hand delivered ten (10) days prior to the commencement of demolition activities.

4.2 Lead-based Paint

A copy of this lead-hazard screen report must be provided to residence within fifteen (15) days of the evaluation. A total of thirty-seven (37) XRF readings were collected during the lead-hazard screen of the building. From the thirty-seven (37) readings, none of them were found to contain toxic levels of lead-based paint.

If the exterior enclosures are impacted during the renovations, the substrate underneath must be assumed to contain toxic levels of lead-based paint and lead safe work practices must be used.

A complete inventory of tested building materials is presented in Detailed Reports contained Appendix 4.

No further action is required regarding lead-based paint. Contractors contemplating work on this project must still comply with the U.S. Department of Labor Occupation Safety and Health Administration (OSHA) 29 CFR 1926.62 Lead Exposure in Construction; Interim Final Rule.

The U.S. Department of Labor Occupation Safety and Health Administration (OSHA) regulates lead dust exposure to workers in the construction industry under 29 CFR 1926.62 Lead Exposure in Construction; Interim Final Rule. Currently, OSHA does not define a threshold level of lead in paint that may cause worker exposure. Any detectable level of lead in paint ($>0.0 \text{ mg/cm}^2 \pm 0.3 \text{ mg/cm}^2$ by XRF or $>0.01 \%$ by AAS) requires task specific exposure monitoring. Contractors performing lead disturbing tasks on this project must comply with the OSHA Lead in Construction Standard.

4.2.1 Dust Hazards

A total of ten (10) dust wipes were collected at the time of inspection. No dust-lead hazards were identified at the sampled locations. Eagle Environmental, Inc. recommends that the residents continue to follow their regular cleaning regimen.

A copy of the dust sample laboratory reports may be found in Appendix 5.

4.2.2 Soil Hazards

Five (5) soil samples were collected from bare areas of soil and gardens from around the site-building. No soil-lead hazards were identified at the sampled locations. The homeowner should maintain the grounds in their current condition.

4.3 Radon

Radon is measured in Picocuries of radon per Liter of air or pCi/L. The USEPA has set a national action level of 4 pCi/L. Ambient concentrations of radon are approximately 0.4 pCi/L of radon for outside air. The USEPA recommends that short term tests that have results of 4 pCi/L or greater be confirmed with a second short-term test. Two short-term tests with results equal to or greater than 4 pCi/L require that radon mitigation be performed.

A review of the Indoor Radon Potential Map of Connecticut indicates a Radon Potential Rating of Moderate (22%). The Radon Potential Rating indicates the percentage of tested homes in this geographical area with basement air radon greater than or equal to 4.0 pCi/l (USEPA Action Level for Radon)

Radon testing was not performed at this Site since the building will be elevated and the lowest level of the building will not be in contact with the ground. Mold

- 4.4 The physical inspection identified visible black mold spore growth on the on the wall studs and insulation in the basement area (Rooms 001-002). The gypsum board ceiling has minor water stains which are likely caused from the basement flooding. There is a strong, pungent odor within the basement area as well.

The porous building materials such as wood and gypsum board will require removal prior to the basement being in-filled. There are no restrictions on the disposal of the porous materials. The basement should be isolated from the main portion of the house during the work.

The mold inspection forms are provided in Appendix 7.

5. COST ESTIMATES

The cost estimates include only the abatement or remediation work necessary to support the renovation/repair work. Other regulated or hazardous materials may be present and were not inspected for under this scope of services and are not included within the estimate.

This is a budgetary opinion of cost that is expected to be within -15 to + 30 percent of the actual cost. Eagle Environmental, Inc. has no control over the cost of labor, materials, equipment or services furnished by others, or over the Contractor or Contractors' methods of determining prices, or over competitive bidding or market conditions. Eagle Environmental, Inc.'s opinion of probable cost of abatement are made on the basis of Eagle Environmental, Inc.'s experience and qualifications and represent Eagle Environmental, Inc.'s judgment as an experienced and qualified consultant familiar with the abatement industry; but Eagle Environmental, Inc. cannot and does not guarantee that proposals, bids or actual Total Project or Abatement Cost will not vary from opinions of probable cost prepared by Eagle Environmental, Inc. If, prior to the bidding or negotiating phase, the Owner wishes greater assurance as to Total Project or Abatement Cost, the Owner shall employ an independent cost estimator.

The cost estimates are provided in Appendix 8.

TABLE I

ASBESTOS-CONTAINING MATERIALS SUMMARY TABLE

TABLE I
ASBESTOS CONTAINING MATERIALS
SUMMARY TABLE
2 APPLETREE LANE
WEST MYSTIC, CONNECTICUT

LOCATION(S)	MATERIAL TYPE	SAMPLE NUMBER	CATEGORY	BULK SAMPLE ANALYSIS RESULTS				ESTIMATED QUANTITY	F/NF	
				PLM	PLM/PC	TEM	NOB			ACM
001	Boiler breeching insulation	7-10-AC-19	TSI	60% Chrys				YES	8 LF on 6" diameter breeching pipe	F
		7-10-AC-20		DNA						
		7-10-AC-21		DNA						
KEY										
DNA = DID NOT ANALYZE										
NAD = NO ASBESTOS DETECTED										
F = FRIABLE										
NF = NON-FRIABLE										
TSI = THERMAL SYSTEMS INSULATION										
SURF = SURFACING MATERIAL										
MISC = MISCELLANEOUS MATERIAL										
ANALYTICAL METHODS										
PLM PC = EPA 600/R-93/116 QUANTITATION 400 POINT COUNT										
TEM NOB = NEW YORK ELAP 198.4 METHOD										
PLM = EPA 600/R-93/116										
PS = Previously Sampled										
EA = Each										
BOLD TEXT IN "LOCATION" COLUMN INDICATES SAMPLE LOCATION										

TABLE II

NON ASBESTOS-CONTAINING MATERIALS SUMMARY TABLE

TABLE II
NON - ASBESTOS CONTAINING MATERIALS
SUMMARY TABLE
2 APPLE TREE LANE
WEST MYSTIC, CONNECTICUT

SAMPLE LOCATION(S)	MATERIAL TYPE	SAMPLE NUMBER	CATEGORY	BULK SAMPLE ANALYSIS RESULTS			
				PLM	PLM PC	TEM NOB	ACM
002	Swirl pattern textured ceiling paint	7-10-AC-01	SURF	NAD			NO
		7-10-AC-02		NAD			
		7-10-AC-03		NAD			
002	Batting insulation paper	7-10-AC-04	MISC	NAD			NO
		7-10-AC-05		NAD			
002	Gypsum board at ceiling	7-10-AC-06	MISC	NAD			NO
		7-10-AC-07		NAD			
002	Sheetrock	7-10-AC-08	MISC	NAD			NO
		7-10-AC-09		NAD			
002	Joint compound	7-10-AC-10	MISC	NAD			NO
		7-10-AC-11		NAD			
002	Sheetrock/joint compound composite	7-10-AC-12	MISC	NAD			NO
		7-10-AC-13		NAD			
		7-10-AC-14		NAD			
002	Textured wall paint on concrete	7-10-AC-15	SURF	NAD			NO
		7-10-AC-16		NAD			
		7-10-AC-17		NAD			
002	White vinyl sheet flooring	7-10-AC-18	MISC	NAD			NO
		7-10-AC-19		NAD			
001	Block mortar	7-10-AC-20	MISC	NAD			NO
		7-10-AC-21		NAD			
001	White cement patch at oil tank penetration	7-10-AC-22	MISC	NAD			NO
		7-10-AC-23		NAD			
		7-10-AC-24		NAD			
Facade A	Exterior textured paint	7-10-AC-25	MISC	NAD			NO
		7-10-AC-26		NAD			
		7-10-AC-27		NAD			
		7-10-AC-28		NAD			
KEY				ANALYTICAL METHODS			
DNA = DID NOT ANALYZE				PLM PC = EPA 600/R-93/116 QUANTIFICATION 400 POINT COUNT			
NAD=NO ASBESTOS DETECTED				TEM NOB = NEW YORK ELAP 198.4 METHOD			
F = FRIABLE				PLM = EPA 600/R-93/116			
NF = NON-FRIABLE				PS = Previously Sampled			
TSI = THERMAL SYSTEMS INSULATION				EA = Each			
SURF = SURFACING MATERIAL							
MISC = MISCELLANEOUS MATERIAL							
BOLD TEXT IN "LOCATION" COLUMN INDICATES SAMPLE LOCATION							

APPENDIX 1
FLOOR PLANS

CAPITAL STUDIOS ARCHITECTS


2 APPLE TREE LANE
MYSTIC, CONNECTICUT

EAGLE PROJECT NUMBER: 14-028.12T17

INDEX OF DRAWINGS

SP-1 SITE PLAN WITH SOIL SAMPLE LOCATIONS
FP-1 BASEMENT PLAN
FP-2 FIRST FLOOR PLAN
FP-3 SECOND FLOOR PLAN


LOCATION MAP



JULY 25, 2014



8 SOUTH MAIN STREET, SUITE 3
TERRYVILLE, CONNECTICUT 06786
860-589-8257



DATE: 07/25/2014
 PROJECT NO.: 14-028.12T17
 DRAWN BY: VB
 REVIEWED BY: AH


ENVIRONMENTAL REVIEW
2 APPLE TREE LANE
MYSTIC, CONNECTICUT

8 SOUTH MAIN STREET, SUITE 3
 TERRYVILLE, CONNECTICUT 06786
 860-589-8257

SHEET NO.

SP-1

SHEET 1 OF 4



8 SOUTH MAIN STREET, SUITE 3
TERRYVILLE, CONNECTICUT 06786
860-589-8257


SHEET NO.

FP-1

SHEET 2 OF 4

DATE: 07/25/2014
PROJECT NO.: 14-028.12T17
DRAWN BY: VB
REVIEWED BY: AH

ENVIRONMENTAL REVIEW
2 APPLE TREE LANE
MYSTIC, CONNECTICUT



8 SOUTH MAIN STREET, SUITE 3
 TERRYVILLE, CONNECTICUT 06786
 860-589-8257

DATE: 07/25/2014
 PROJECT NO.: 14-028.12T17
 DRAWN BY: VB
 REVIEWED BY: AH

ENVIRONMENTAL REVIEW
2 APPLE TREE LANE
MYSTIC, CONNECTICUT

SHEET NO.


FP-2

SHEET 3 OF 4

SIDE-C

SIDE-B

SIDE-D



SECOND FLOOR

NOT TO SCALE

SIDE-A (STREET SIDE)



EAGLE
Environmental, Inc.

8 SOUTH MAIN STREET, SUITE 3
TERRYVILLE, CONNECTICUT 06786
860-589-8257

SHEET NO.

FP-3

SHEET 4 OF 4

DATE: 07/25/2014
PROJECT NO.: 14-028.12T17
DRAWN BY: VB
REVIEWED BY: AH

ENVIRONMENTAL REVIEW
2 APPLE TREE LANE
MYSTIC, CONNECTICUT

APPENDIX 2

ASBESTOS BULK SAMPLE LABORATORY REPORTS

(*) REVISED (*) 031426848



EMSL - MA 7 Constitution Way, Ste 107 Woburn, MA 01801 (781) 933-8411 (781) 933-8412 Fax	EMSL - CT 29 N. Plains Hwy, Unit 4 Wallingford, CT 06482 (203) 284-5948 (203) 284-5978 Fax	EMSL - NY 307 West 38 th Street New York, NY 10018 (866) 448-3675 (212) 290-0058 Fax	EMSL - NJ 107 Haddon Avenue Westmont, NJ 08108 (800) 220-3675 (856) 858-4960 Fax
---	---	--	---

Your Name: Brandy LeBlanc **Project Manager:** PF
Company: Eagle Environmental, Inc.
Street: 8 South Main Street, Suite 3
City/State/Zip: Terryville, CT 06786
Phone: 860-589-8257 ext. 203 **Fax:** 860-586-7034 **Email:** bleblanc@eagleenviro.com; nporter@eagleenviro.com; dwynne@eagleenviro.com; rsloch@eagleenviro.com
Project Name: CSA Super Storm Sandy **Project #:** 14-028.12T17
Project Location: 2 Appletree Lane, Mystic **Project State (US):** CT

TURNAROUND TIME

3 Hours
 6 Hours
 24 Hours
 48 Hours
 72 Hours
 4 Days
 5 Days
 6-10 Days

SAMPLE MATRIX

Air
 Bulk
 Soil
 Wipe
 Micro-Vac
 Drinking Water
 Wastewater
 Chips
 Other

ASBESTOS ANALYSIS

PCM - Air
 NIOSH 7400 (A) Issue 2: August 1994
 OSHA w/TWA
TEM AIR
 AHERA 40 CFR, Part 763 Subpart E
 NIOSH 7402 Issue 2
 EPA Level II
PLM - Bulk
 EPA 600/R-93/116
 NY Stratified Point Count
 California Air Resource Board (CARB) 435
 NIOSH 9802
 PLM NOB (Gravimetric) NYS 198.1
 EPA Point Count (400 Points)
 EPA Point Count (1,000 Points)
 Standard Addition Point Count
SOILS
 EPA Protocol Qualitative
 EPA Protocol Quantitative
 EMSL MSD 9000 Method fibers/gram
 Superfund EPA 640-R097-028 (dust generation)
TEM BULK
 Drop Mount (Qualitative)
 Chatfield SOP-1988-02
 TEM NOB (Gravimetric) NY 198.4
TEM MICROVAC
 ASTM D 5755-95 (Quantitative)
TEM WIPE
 ASTM D-6480-99
 Qualitative
TEM WATER
 EPA 100.1
 EPA 100.2
 NYS 198.2
 Other:

LEAD ANALYSIS

Flame Atomic Absorption
 Wipe, SW846-7420 ASTM non ASTM
 Soil, SW846-7420
 Air, NIOSH 7082
 Chips, SW846-7420 or AOC 5.009 (974.02)
 Wastewater, SW 846-7420
 TCLP LEAD SW846-1311/7420
Graphite Furnace Atomic Absorption
 Air, NIOSH 7106
 Wastewater, SW846-7421
 Soil, SW846-7421
 Drinking Water, EPA 239.2
ICP - Inductively Coupled Plasma
 Wipe, SW846-6010 ASTM non ASTM
 Soil, SW846-6010
 Air, NIOSH 7300

MATERIALS ANALYSIS

Full Particle Identification
 Optical Particle Identification
 Dust Mitas and Insect Fragments
 Particle Size & Distribution
 Product Comparison
 Paint Characterization
 Failure Analysis
 Corrosion Analysis
 Glove Box Containment Study
 Petrographic Examination of Concrete
 Portland Cement in Workplace Atmospheres (OSHA ID-143)
 Man Made Vitreous Fibers - MMVF's
 Synthetic Fiber Identification
 Other:

MICROBIAL ANALYSIS

Air Samples
 Mold & Fungi by Air O Cell
 Mold & Fungi by Agar Plate count & Id
 Bacterial Count and Gram Stain
 Bacterial Count and Identification
Water Samples
 Total Coliforms, Fecal Coliforms
 Escherichia Coli, Fecal Streptococcus
 Legionella
 Salmonella
 Giardia and Cryptosporidium
Wipe and Bulk Samples
 Mold & Fungi - Direct Examination
 Mold & Fungi - (Culture follow up to direct examination if necessary)
 Mold & Fungi - Culture (Count & ID)
 Mold & Fungi - Culture (Count only)
 Bacterial Count & Gram Stain
 Bacterial Count & Identification (3 most prominent types)
 Other:

IAQ ANALYSIS

Nuisance Dust (NIOSH 0500 & 0600)
 Airborne Dust (PM10, TSP)
 Silica Analysis by XRD NIOSH 7500
 HVAC Efficiency
 Carbon Black
 Airborne Oil Mist
 Other:

Additional information/Comments/Instructions: ****PLEASE STOP ON 1ST POSITIVE WITHIN SETS**

Client Sample # (S)	7-10-AC-01	7-10-AC-28	TOTAL SAMPLE #
Relinquished:	ANDREW CARNEVALE <i>Andrew Carnevale</i>	Date: 7-10-2014	Time: PM
Received:	NANCY PORTER <i>Nancy Porter</i>	Date: 7-10-2014	Time: PM
Relinquished:	NANCY PORTER <i>Nancy Porter</i>	Date: 7-10-2014	Time: PM
Received:	<i>LeBlanc</i>	Date: 7/11/14	Time: 9:58am



EMSL – MA 7 Constitution Way, Ste 107 Woburn, MA 01801 (781) 933-8411 (781) 933-8412 Fax	EMSL – CT 29 N. Plains Hwy, Unit 4 Wallingford, CT 06492 (203) 284-5948 (203) 284-5978 Fax	EMSL – NY 307 West 38 th Street New York, NY 10018 (866) 448-3675 (212) 290-0058 Fax	EMSL – NJ 107 Haddon Avenue Westmont, NJ 08108 (800) 220-3675 (856) 858-4960 Fax
---	---	--	---

SAMPLE NUMBER	SAMPLE DESCRIPTION	ROOM or LOCATION	VOLUME Air (L)	Area (Inches sq.)
7-10-AC-01	Swirl pattern textured ceiling paint	002		NAD
7-10-AC-02	Swirl pattern textured ceiling paint	002		
7-10-AC-03	Swirl pattern textured ceiling paint	002		
7-10-AC-04	Battling Insulation paper	002		
7-10-AC-05	Battling Insulation paper	002		
7-10-AC-06	Gypsum board at ceiling	002		
7-10-AC-07	Gypsum board at ceiling	002		
7-10-AC-08	Sheetrock	002		
7-10-AC-09	Sheetrock	002		
7-10-AC-10	Joint compound	002		
7-10-AC-11	Joint compound	002		
7-10-AC-12	Sheetrock/joint compound composite	002		
7-10-AC-13	Sheetrock/joint compound composite	002		
7-10-AC-14	Textured wall paint on concrete	002		
7-10-AC-15	Textured wall paint on concrete	002		
7-10-AC-16	Textured wall paint on concrete	002		
7-10-AC-17	White vinyl sheet flooring	002		
7-10-AC-18	White vinyl sheet flooring	002		
7-10-AC-19	Breaching insulation	001		60% chips
7-10-AC-20	Breaching insulation	001		DNA
7-10-AC-21	Breaching insulation	001		DNA
7-10-AC-22	Block mortar	001		NAD
7-10-AC-23	Block mortar	001		
7-10-AC-24	White cement patch at oil tank penetration	001		
7-10-AC-25	White cement patch at oil tank penetration	001		

**EMSL Analytical, Inc.**

307 West 38th Street, New York, NY 10018

Phone/Fax: (212) 290-0051 / (212) 290-0058

<http://www.EMSL.com>manhattanlab@emsl.com

EMSL Order: 031426848

CustomerID: EEVM50

CustomerPO:

ProjectID:

Attn: **Eagle Environmental, Inc. - CT**
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
 Fax: (860) 585-7034
 Received: 07/11/14 9:58 AM
 Analysis Date: 7/12/2014
 Collected: 7/10/2014

Project: 14-028.12T17/ CSA SUPER STORM SANDY/ 2 APPLETREE LANE, MYSTIC

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
7-10-AC-01 031426848-0001	002 - SWIRL PATTERN TEXTURED CEILING PAINT	Tan/White Non-Fibrous Homogeneous		4% Mica 60% Ca Carbonate 36% Non-fibrous (other)	None Detected
7-10-AC-02 031426848-0002	002 - SWIRL PATTERN TEXTURED CEILING PAINT	White Non-Fibrous Homogeneous		5% Mica 60% Ca Carbonate 35% Non-fibrous (other)	None Detected
7-10-AC-03 031426848-0003	002 - SWIRL PATTERN TEXTURED CEILING PAINT	White Non-Fibrous Homogeneous		3% Mica 75% Ca Carbonate 22% Non-fibrous (other)	None Detected
7-10-AC-04 031426848-0004	002 - BATTING INSULATION PAPER	Brown Fibrous Homogeneous	80% Cellulose 4% Glass	16% Non-fibrous (other)	None Detected
7-10-AC-05 031426848-0005	002 - BATTING INSULATION PAPER	Brown/Black Fibrous Homogeneous	4% Glass 65% Cellulose	31% Non-fibrous (other)	None Detected
7-10-AC-06 031426848-0006	002 - GYPSUM BOARD AT CEILING	Gray Fibrous Homogeneous	<1% Cellulose	65% Quartz 35% Non-fibrous (other)	None Detected
7-10-AC-07 031426848-0007	002 - GYPSUM BOARD AT CEILING	Gray Non-Fibrous Homogeneous	2% Cellulose	55% Gypsum 43% Non-fibrous (other)	None Detected
7-10-AC-08 031426848-0008	002 - SHEETROCK	Gray Non-Fibrous Homogeneous	<1% Cellulose	65% Gypsum 35% Non-fibrous (other)	None Detected
7-10-AC-09 031426848-0009	002 - SHEETROCK	Brown/Gray Fibrous Homogeneous	3% Cellulose	68% Gypsum 29% Non-fibrous (other)	None Detected

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. New York, NY AIHA-LAP, LLC-IHLAP Accredited #102581, NVLAP Lab Code 101048-9, NYS ELAP 11506, NJ NY022, CT PH-0170, MA AA000170

Report Amended: 07/18/2014 23:06:44 Replaces the Initial Report 07/12/2014 03:48:57. Reason Code: Data Entry-Change to Project

**EMSL Analytical, Inc.**

307 West 38th Street, New York, NY 10018

Phone/Fax: (212) 290-0051 / (212) 290-0058

<http://www.EMSL.com>manhattanlab@emsl.com

EMSL Order: 031426848

CustomerID: EEVM50

CustomerPO:

ProjectID:

Attn: **Eagle Environmental, Inc. - CT**
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
 Fax: (860) 585-7034
 Received: 07/11/14 9:58 AM
 Analysis Date: 7/12/2014
 Collected: 7/10/2014

Project: 14-028.12T17/ CSA SUPER STORM SANDY/ 2 APPLETREE LANE, MYSTIC

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
7-10-AC-10 031426848-0010	002 - JOINT COMPOUND	White Fibrous Homogeneous	<1% Cellulose	65% Ca Carbonate 35% Non-fibrous (other)	None Detected
7-10-AC-11 031426848-0011	002 - JOINT COMPOUND	White Non-Fibrous Homogeneous		2% Mica 65% Ca Carbonate 33% Non-fibrous (other)	None Detected
7-10-AC-12 031426848-0012	002 - SHEETROCK/JOINT COMPOUND COMPOSITE	Brown/Gray/White Fibrous Homogeneous	<1% Cellulose	60% Gypsum 12% Ca Carbonate 28% Non-fibrous (other)	None Detected
7-10-AC-13 031426848-0013	002 - SHEETROCK/JOINT COMPOUND COMPOSITE	Brown/Gray/White Fibrous Homogeneous	8% Cellulose	45% Gypsum 20% Ca Carbonate 27% Non-fibrous (other)	None Detected
7-10-AC-14 031426848-0014	002 - TEXTURED WALL PAINT ON CONCRETE	Gray Non-Fibrous Homogeneous	3% Cellulose	6% Quartz 55% Ca Carbonate 36% Non-fibrous (other)	None Detected
7-10-AC-15 031426848-0015	002 - TEXTURED WALL PAINT ON CONCRETE	Gray Non-Fibrous Homogeneous		4% Quartz 60% Ca Carbonate 36% Non-fibrous (other)	None Detected
7-10-AC-16 031426848-0016	002 - TEXTURED WALL PAINT ON CONCRETE	Gray Non-Fibrous Homogeneous		10% Quartz 45% Ca Carbonate 45% Non-fibrous (other)	None Detected
7-10-AC-17 031426848-0017	002 - WHITE VINYL SHEET FLOORING	Tan/Red Non-Fibrous Homogeneous		100% Non-fibrous (other)	None Detected

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. New York, NY AIHA-LAP, LLC-IHLAP Accredited #102581, NVLAP Lab Code 101048-9, NYS ELAP 11506, NJ NY022, CT PH-0170, MA AA000170

Report Amended: 07/18/2014 23:06:44 Replaces the Initial Report 07/12/2014 03:48:57. Reason Code: Data Entry-Change to Project

**EMSL Analytical, Inc.**

307 West 38th Street, New York, NY 10018

Phone/Fax: (212) 290-0051 / (212) 290-0058

<http://www.EMSL.com>manhattanlab@emsl.com

EMSL Order: 031426848

CustomerID: EEVM50

CustomerPO:

ProjectID:

Attn: **Eagle Environmental, Inc. - CT**
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
 Fax: (860) 585-7034
 Received: 07/11/14 9:58 AM
 Analysis Date: 7/12/2014
 Collected: 7/10/2014

Project: 14-028.12T17/ CSA SUPER STORM SANDY/ 2 APPLETREE LANE, MYSTIC

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
7-10-AC-18 031426848-0018	002 - WHITE VINYL SHEET FLOORING	Tan Non-Fibrous Homogeneous	2% Cellulose	15% Ca Carbonate 45% Matrix 38% Non-fibrous (other)	None Detected
7-10-AC-19 031426848-0019	001 - BREECHING INSULATION	Gray Fibrous Homogeneous	10% Cellulose	30% Non-fibrous (other)	60% Chrysotile
7-10-AC-20 031426848-0020	001 - BREECHING INSULATION				Stop Positive (Not Analyzed)
7-10-AC-21 031426848-0021	001 - BREECHING INSULATION				Stop Positive (Not Analyzed)
7-10-AC-22 031426848-0022	001 - BLOCK MORTAR	Gray Non-Fibrous Homogeneous		60% Quartz 18% Ca Carbonate 22% Non-fibrous (other)	None Detected
7-10-AC-23 031426848-0023	001 - BLOCK MORTAR	Gray Non-Fibrous Homogeneous		68% Quartz 32% Non-fibrous (other)	None Detected
7-10-AC-24 031426848-0024	001 - WHITE CEMENT PATCH AT OIL TANK PENTRATION	Gray Non-Fibrous Homogeneous		50% Quartz 15% Ca Carbonate 35% Non-fibrous (other)	None Detected
7-10-AC-25 031426848-0025	001 - WHITE CEMENT PATCH AT OIL TANK PENTRATION	Gray/White Non-Fibrous Homogeneous		45% Quartz 55% Non-fibrous (other)	None Detected

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. New York, NY AIHA-LAP, LLC-IHLAP Accredited #102581, NVLAP Lab Code 101048-9, NYS ELAP 11505, NJ NY022, CT PH-0170, MA AA000170

Report Amended: 07/18/2014 23:06:44 Replaces the Initial Report 07/12/2014 03:48:57. Reason Code: Data Entry-Change to Project

**EMSL Analytical, Inc.**

307 West 38th Street, New York, NY 10018
 Phone/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> manhattanlab@emsl.com

EMSL Order: 031426848
 CustomerID: EEVM50
 CustomerPO:
 ProjectID:

Attn: **Eagle Environmental, Inc. - CT**
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
 Fax: (860) 585-7034
 Received: 07/11/14 9:58 AM
 Analysis Date: 7/12/2014
 Collected: 7/10/2014

Project: 14-028.12T17/ CSA SUPER STORM SANDY/ 2 APPLETREE LANE, MYSTIC

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
7-10-AC-26 031426848-0026	FAC A - EXTERIOR TEXTURED PAINT	Gray Non-Fibrous Homogeneous		55% Quartz 25% Ca Carbonate 20% Non-fibrous (other)	None Detected
7-10-AC-27 031426848-0027	FAC A - EXTERIOR TEXTURED PAINT	Gray Non-Fibrous Homogeneous		40% Quartz 15% Ca Carbonate 45% Non-fibrous (other)	None Detected
7-10-AC-28 031426848-0028	FAC A - EXTERIOR TEXTURED PAINT	Gray Non-Fibrous Homogeneous		42% Quartz 3% Mica 55% Non-fibrous (other)	None Detected

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
 Samples analyzed by EMSL Analytical, Inc. New York, NY AIHA-LAP, LLC-IHLAP Accredited #102581, NVLAP Lab Code 101048-9, NYS ELAP 11506, NJ NY022, CT PH-0170, MA AA000170

Report Amended: 07/18/2014 23:06:44 Replaces the Initial Report 07/12/2014 03:48:57. Reason Code: Data Entry-Change to Project



EMSL Analytical, Inc.

307 West 38th Street, New York, NY 10018
Phone/Fax (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> manhattanlab@emsl.com

EMSL Order: 031426848
CustomerID: EEVM50
CustomerPO:
ProjectID:

Attn: **Eagle Environmental, Inc. - CT**
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
Fax: (860) 585-7034
Received: 07/11/14 9:58 AM
Analysis Date: 7/12/2014
Collected: 7/10/2014

Project: 14-028.12T17/ CSA SUPER STORM SANDY/ 2 APPLETREE LANE, MYSTIC

The samples in this report were submitted to EMSL for analysis by Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy. The reference number for these samples is the EMSL Order ID above. Please use this reference number when calling about these samples.

Report Comments:

Sample Receipt Date:: 7/11/2014 Sample Receipt Time: 9:58 AM
Analysis Completed Date: 7/12/2014 Analysis Completed Time: 12:02 AM

Analyst(s):

Keri-Dean Scarlett PLM (15)

Shahrakur Mahmud PLM (11)

Samples reviewed and approved by:

James Hall, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (f.e. linoleum, wallboard, etc.) are reported as a single sample. Reporting limit is 1%
Samples analyzed by EMSL Analytical, Inc. New York, NY AIHA-LAP, LLC-IHLAP Accredited #102581, NVLAP Lab Code 101048-9, NYS ELAP 11506, NJ NY022, CT PH-0170, MA AA000170

Report Amended: 07/18/2014 23:06:44 Replaces the Initial Report 07/12/2014 03:48:57. Reason Code: Data Entry-Change to Project

APPENDIX 3

INTERIOR AND EXTERIOR VISUAL ASSESSMENT FORMS



EAGLE Environmental, Inc.

INTERIOR VISUAL ASSESSMENT FORM

Address: 2 Apple Tree Lane, Mystic

Room No: 002 Basement * Most material has been removed already

COMPONENT	SIDE	RATING	NOTES	INTERIM CONTROL
Floor	A B C D	I F (P)	concrete - XRF	
Wall	A B C D	I F P	var + lead - XRF	
Ceiling	A B C D	(1) F P	XRF - Mold observed	
Door	A B C D	(1) F P		
Door Casing	A B C D	(1) F P	new pre-hung	
Door Jamb	A B C D	(1) F P		
Baseboard	A B C D	I F P		
Window Casing	A B C D	I F P		
Window Stop	A B C D	I F P		
Window Jamb	A B C D	I F P		
Window Sash	A B C D	I F P		
Window Well	A B C D	I F P		
Window Sill	A B C D	I F P		
Window Apron	A B C D	I F P		
Closet Door	A B C D	I F P		
Closet Door Casing	A B C D	I F P		
Closet Door Jamb	A B C D	I F P		
Closet Shelf	A B C D	I F P		
Shelf Support	A B C D	I F P		
Radiator	A B C D	I F P		
Crown Molding	A B C D	I F P		
Cabinet	A B C D	I F P		
Cabinet Door	A B C D	I F P		
Cabinet Frame	A B C D	I F P		
Columns	A B C D	I F (P)	XRF	
Beam	A B C D	I F (P)	XRF	
Stair treads	A B C D	(1) F P	varnish XRF	
risers	A B C D	I F (P)	paint XRF	
Dec wall by stairs	A B C D	(1) F P	XRF	
Studs	A B C D	I F (P)	No paint - mold observed - XRF	
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		



EAGLE Environmental, Inc.

INTERIOR VISUAL ASSESSMENT FORM

Address: 2 Apple Tree Lane, Mystic

Room No: 009 Bath 2 (Mastic)

COMPONENT	SIDE	RATING	NOTES	INTERIM CONTROL
Floor	A B C D	① F P	linoleum	
Wall	A B C D	① F P		
Ceiling	A B C D	① F P		
Door	A B C D	① F P		
Door Casing	A B C D	① F P		
Door Jamb	A B C D	① F P		
Baseboard	A B C D	① F P		
Window Casing	A B C D	① F P		
Window Stop	A B C D	① F P		
Window Jamb	A B C D	I F P	replacement window	
Window Sash	A B C D	I F P		
Window Well	A B C D	I F P		
Window Sill	A B C D	① F P		
Window Apron	A B C D	① F P		
Closet Door	A B C D	I F P		
Closet Door Casing	A B C D	I F P		
Closet Door Jamb	A B C D	I F P		
Closet Shelf	A B C D	I F P		
Shelf Support	A B C D	I F P		
Radiator	A B C D	I F P		
Crown Molding	A B C D	I F P		
Cabinet	A B C D	I F P		
Cabinet Door	A B C D	I F P		
Cabinet Frame	A B C D	I F P		
shelving	A B C D	① F P		
shelf supp.	A B C D	① F P		
low wall beadboard	A B C D	① F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		



EAGLE Environmental, Inc.

INTERIOR VISUAL ASSESSMENT FORM

Address: 2 Apple Tree Lane, Mystic

Room No: on Hallway

COMPONENT	SIDE	RATING	NOTES	INTERIM CONTROL
Floor	A B C D	① F P	varnished	
Wall	① ② ③ ④	① F P		
Ceiling	A B C D	① F P		
Door	A B ③ ④	① F P		
Door Casing	A ③ ④	① F P		
Door Jamb	A B C D	I F P		
Baseboard	A ③ ④	① F P		
Window Casing	A B C D	I F P		
Window Stop	A B C D	I F P		
Window Jamb	A B C D	I F P		
Window Sash	A B C D	I F P		
Window Well	A B C D	I F P		
Window Sill	A B C D	I F P		
Window Apron	A B C D	I F P		
Closet Door	A B C D	I F P		
Closet Door Casing	A B C D	I F P		
Closet Door Jamb	A B C D	I F P		
Closet Shelf	A B C D	I F P		
Shelf Support	A B C D	I F P		
Radiator	A B C D	I F P		
Crown Molding	A B C D	I F P		
Cabinet	A B C D	I F P		
Cabinet Door	A B C D	I F P		
Cabinet Frame	A B C D	I F P		
Stair treads	A B C D	① F P	varnished	
risers	A B C D	I F ②	XRF	
Stringer	A B C D	① F P		
handrail	A B C D	① F P	varnished	
Attic pull-down	A B C D	① F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		



EAGLE Environmental, Inc.

INTERIOR VISUAL ASSESSMENT FORM

Address: 2 Apple Tree Lane, Mystic

Room No: 012 Garage

COMPONENT	SIDE	RATING	NOTES	INTERIM CONTROL
Floor	A B C D	① F P	concrete	
Wall	① A B C D	① F P		
Ceiling	A B C D	① F P		
Door	① A B C D	① F P	pre-hung	
Door Casing	① A B C D	① F P		
Door Jamb	① A B C D	① F P		
Baseboard	A B C D	I F P		
Window Casing	A B C D	I F P		
Window Stop	A B C D	I F P		
Window Jamb	A B C D	I F P		
Window Sash	A B C D	I F P		
Window Well	A B C D	I F P		
Window Sill	A B C D	I F P		
Window Apron	A B C D	I F P		
Closet Door	A B C D	I F P		
Closet Door Casing	A B C D	I F P		
Closet Door Jamb	A B C D	I F P		
Closet Shelf	A B C D	I F P		
Shelf Support	A B C D	I F P		
Radiator	A B C D	I F P		
Crown Molding	A B C D	I F P		
Cabinet	A B C D	I F P		
Cabinet Door	A B C D	I F P		
Cabinet Frame	A B C D	I F P		
overhead doors	① A B C D	① F P	vinyl replacements	
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		
	A B C D	I F P		

APPENDIX 4

XRF LEAD-BASED PAINT INSPECTION REPORTS

LEAD PAINT INSPECTION REPORT

REPORT NUMBER: S#02753 - 07/10/14 11:40

INSPECTION FOR: Mr. David Holmes
Capital Studio Architects
1379 Main Street
East Hartford, CT 06106

PERFORMED AT: 2 Apple Tree Lane
Mystic, CT

INSPECTION DATE: 07/10/14

INSTRUMENT TYPE: R M D
MODEL LPA-1
XRF TYPE ANALYZER
Serial Number: 02753

ACTION LEVEL: 1.0 mg/cm²

OPERATOR LICENSE: 002206

A Lead-Based Paint Screen was performed for the interiors and exteriors.

SIGNED: _____



Kristen Liljehult
Lead Inspector / Risk Assessor
Eagle Environmental, Inc.
8 South Main Street, Suite # 3
Terryville, CT 06786

Date: _____

7/10/14

SUMMARY REPORT OF LEAD PAINT INSPECTION FOR: Mr. David Holmes

Inspection Date: 07/10/14 2 Apple Tree Lane
Report Date: 7/10/2014 Mystic, CT
Abatement Level: 1.0
Report No. S#02753 - 07/10/14 11:40
Total Readings: 37 Actionable: 0
Job Started: 07/10/14 11:40
Job Finished: 07/10/14 14:00

Reading					Paint				Lead
No.	Wall	Structure	Location	Member	Cond	Substrate	Color	(mg/cm ²)	Mode

Calibration Readings

---- End of Readings ----

DETAILED REPORT OF LEAD PAINT INSPECTION FOR: Mr. David Holmes

Reading No.	Wall	Structure	Location	Member	Paint Cond	Substrate	Color	Lead (mg/cm ²)	Mode
032	-	Stairs	Ctr	Risers	P	Wood	white	-0.3	QM

Calibration Readings

001								1.0	TC
002								1.0	TC
003								1.0	TC
035								1.0	TC
036								1.0	TC
037								1.1	TC

---- End of Readings ----

APPENDIX 5

LEAD DUST AND SOIL SAMPLE LABORATORY REPORTS

031426773



www.emsl.com

EMSL - MA 7 Constitution Way, Ste 107 Woburn, MA 01801 (781) 933-8411 (781) 933-8412 Fax	EMSL - CT 29 N. Plains Hwy, Unit 4 Wallingford, CT 06492 (203) 284-5948 (203) 284-5978 Fax	EMSL - NY 307 West 38 th Street New York, NY 10018 (866) 448-3675 (212) 290-0058 Fax	EMSL - NJ 107 Haddon Avenue Westmont, NJ 08108 (800) 220-3675 (856) 858-4960 Fax
---	---	--	---

Your Name: Brandy LeBlanc **Project Manager:**

Company: Eagle Environmental, Inc.

Street: 8 South Main Street, Suite 3

City/State/Zip: Terryville, CT 06786

Phone: 860-589-8257 ext. 203 **Fax:** 860-585-7034 **Email:** bleblanc@eagleenviro.com; nporter@eagleenviro.com; dwynne@eagleenviro.com; rsoch@eagleenviro.com

Project Name: Capital Studio Architects - Environmental Review **Project #:** 14-028.12T17

Project Location: 2 Apple Tree Lane, Mystic **Project State (US):** CT

TURNAROUND TIME

3 Hours
 6 Hours
 24 Hours
 48 Hours
 72 Hours
 4 Days
 5 Days
 6-10 Days

SAMPLE MATRIX

Air
 Bulk
 Soil
 Wipe
 Micro-Vac
 Drinking Water
 Wastewater
 Chips
 Other

<p>ASBESTOS ANALYSIS</p> <p>PCM - Air</p> <p><input type="checkbox"/> NIOSH 7400 (A) Issue 2: August 1994</p> <p><input type="checkbox"/> OSHA w/TWA</p> <p>TEM AIR</p> <p><input type="checkbox"/> AHERA 40 CFR, Part 763 Subpart E</p> <p><input type="checkbox"/> NIOSH 7402 Issue 2</p> <p><input type="checkbox"/> EPA Level II</p> <p>PLM - Bulk</p> <p><input checked="" type="checkbox"/> EPA 600/R-93/116</p> <p><input type="checkbox"/> NY Stratified Point Count</p> <p><input type="checkbox"/> California Air Resource Board (CARB) 435</p> <p><input type="checkbox"/> NIOSH 9002</p> <p><input type="checkbox"/> PLM NOB (Gravimetric) NYS 198.1</p> <p><input type="checkbox"/> EPA Point Count (400 Points)</p> <p><input type="checkbox"/> EPA Point Count (1,000 Points)</p> <p><input type="checkbox"/> Standard Addition Point Count</p> <p>SOILS</p> <p><input type="checkbox"/> EPA Protocol Qualitative</p> <p><input type="checkbox"/> EPA Protocol Quantitative</p> <p><input type="checkbox"/> EMSL MSD 9000 Method fibers/gram</p> <p><input type="checkbox"/> Superfund EPA 540-R097-028 (dust generation)</p> <p>TEM BULK</p> <p><input type="checkbox"/> Drop Mount (Qualitative)</p> <p><input type="checkbox"/> Chatfield SOP-1988-02</p> <p><input type="checkbox"/> TEM NOB (Gravimetric) NY 198.4</p> <p>TEM MICROVAC</p> <p><input type="checkbox"/> ASTM D 5755-95 (Quantitative)</p> <p>TEM WIPE</p> <p><input type="checkbox"/> ASTM D-6480-99</p> <p><input type="checkbox"/> Qualitative</p> <p>TEM WATER</p> <p><input type="checkbox"/> EPA 100.1</p> <p><input type="checkbox"/> EPA 100.2</p> <p><input type="checkbox"/> NYS 198.2</p> <p><input type="checkbox"/> Other:</p>	<p>LEAD ANALYSIS</p> <p>Flame Atomic Absorption</p> <p><input type="checkbox"/> Wipe, SW846-7420 <input type="checkbox"/> ASTM <input type="checkbox"/> non ASTM</p> <p><input checked="" type="checkbox"/> Soil, SW846-7420</p> <p><input type="checkbox"/> Air, NIOSH 7082</p> <p><input type="checkbox"/> Chips, SW846-7420 or AOAC 5.009 (974.02)</p> <p><input type="checkbox"/> Wastewater, SW 846-7420</p> <p><input type="checkbox"/> TCLP LEAD SW846-1311/7420</p> <p>Graphite Furnace Atomic Absorption</p> <p><input type="checkbox"/> Air, NIOSH 7105</p> <p><input type="checkbox"/> Wastewater, SW846-7421</p> <p><input type="checkbox"/> Soil, SW846-7421</p> <p><input type="checkbox"/> Drinking Water, EPA 239.2</p> <p>ICP - Inductively Coupled Plasma</p> <p><input type="checkbox"/> Wipe, SW846-6010 <input type="checkbox"/> ASTM <input type="checkbox"/> non ASTM</p> <p><input type="checkbox"/> Soil, SW846-6010</p> <p><input type="checkbox"/> Air, NIOSH 7300</p> <p>MATERIALS ANALYSIS</p> <p><input type="checkbox"/> Full Particle Identification</p> <p><input type="checkbox"/> Optical Particle Identification</p> <p><input type="checkbox"/> Dust Mites and Insect Fragments</p> <p><input type="checkbox"/> Particle Size & Distribution</p> <p><input type="checkbox"/> Product Comparison</p> <p><input type="checkbox"/> Paint Characterization</p> <p><input type="checkbox"/> Failure Analysis</p> <p><input type="checkbox"/> Corrosion Analysis</p> <p><input type="checkbox"/> Glove Box Containment Study</p> <p><input type="checkbox"/> Petrographic Examination of Concrete</p> <p><input type="checkbox"/> Portland Cement in Workplace Atmospheres (OSHA ID-143)</p> <p><input type="checkbox"/> Man Made Vitrous Fibers - MMVF's</p> <p><input type="checkbox"/> Synthetic Fiber Identification</p> <p><input type="checkbox"/> Other:</p>	<p>MICROBIAL ANALYSIS</p> <p>Air Samples</p> <p><input type="checkbox"/> Mold & Fungi by Air O Cell</p> <p><input type="checkbox"/> Mold & Fungi by Agar Plate count & id</p> <p><input type="checkbox"/> Bacterial Count and Gram Stain</p> <p><input type="checkbox"/> Bacterial Count and Identification</p> <p>Water Samples</p> <p><input type="checkbox"/> Total Coliforms, Fecal Coliforms</p> <p><input type="checkbox"/> Escherichia Coli, Fecal Streptococcus</p> <p><input type="checkbox"/> Legionella</p> <p><input type="checkbox"/> Salmonella</p> <p><input type="checkbox"/> Giardia and Cryptosporidium</p> <p>Wipe and Bulk Samples</p> <p><input type="checkbox"/> Mold & Fungi - Direct Examination</p> <p><input type="checkbox"/> Mold & Fungi - (Culture follow up to direct examination if necessary)</p> <p><input type="checkbox"/> Mold & Fungi - Culture (Count & ID)</p> <p><input type="checkbox"/> Mold & Fungi - Culture (Count only)</p> <p><input type="checkbox"/> Bacterial Count & Gram Stain</p> <p><input type="checkbox"/> Bacterial Count & Identification (3 most prominent types)</p> <p><input type="checkbox"/> Other:</p> <p>IAQ ANALYSIS</p> <p><input type="checkbox"/> Nuisance Dust (NIOSH 0500 & 0600)</p> <p><input type="checkbox"/> Airborne Dust (PM10, TSP)</p> <p><input type="checkbox"/> Silica Analysis by XRD <input type="checkbox"/> Niosh 7500</p> <p><input type="checkbox"/> HVAC Efficiency</p> <p><input type="checkbox"/> Carbon Black</p> <p><input type="checkbox"/> Airborne Oil Mist</p> <p><input type="checkbox"/> Other:</p>
--	---	--

Additional Information/Comments/Instructions: ****PLEASE STOP ON 1ST POSITIVE WITHIN SETS**

Client Sample # (S)	7/10 KL 01	7/10 KL 10	TOTAL SAMPLE #
Relinquished:	Kristen Liljeblut	Date: 7/10/14	Time: P.M.
Received:	<i>[Signature]</i>	Date: 7-10-14	Time: P.M.
Relinquished:	<i>[Signature]</i>	Date: 7-10-14	Time: P.M.
Received:	<i>[Signature]</i>	Date: 7/11/14	Time: 10:10 AM

**EMSL Analytical, Inc.**

307 West 38th Street, New York, NY 10018
 Phone/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> manhattanlab@emsl.com

EMSL Order: 031426773
 CustomerID: EEVM50
 CustomerPO:
 ProjectID:

Attn: **Brandy LeBlanc**
Eagle Environmental, Inc. - CT
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
 Fax: (860) 585-7034
 Received: 07/11/14 10:10 AM
 Collected: 7/10/2014

Project: 14-028.12T17/ CAPITAL STUDIO ARCHITECTS-ENVIRONMENTAL REVIEW/ 2 APPLE TREE LANE, MYSTIC, CT

Test Report: Lead in Dust by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Area Sampled</i>	<i>Lead Concentration</i>
7/10 KL 01 Site: FIELD BLANK	0001	7/10/2014	7/11/2014	n/a	<10 µg/wipe
7/10 KL 02 Site: FIELD BLANK	0002	7/10/2014	7/11/2014	n/a	<10 µg/wipe
7/10 KL 03 Site: FLOOR AT "A" ENTRY LIVING RM	0003	7/10/2014	7/11/2014	144 in ²	<10 µg/ft ²
7/10 KL 04 Site: FLOOR AT "B" ENTRY LIVING RM	0004	7/10/2014	7/11/2014	144 in ²	<10 µg/ft ²
7/10 KL 05 Site: WINDOW WELL LIVING RM	0005	7/10/2014	7/11/2014	120 in ²	48 µg/ft ²
7/10 KL 06 Site: WINDOW SILL KIT/DINING	0006	7/10/2014	7/11/2014	56 in ²	<26 µg/ft ²
7/10 KL 07 Site: FLOOR BATHROOM 1	0007	7/10/2014	7/11/2014	144 in ²	<10 µg/ft ²
7/10 KL 08 Site: WINDOW SILL BATHROOM 1	0008	7/10/2014	7/11/2014	41.25 in ²	<35 µg/ft ²
7/10 KL 09 Site: FLOOR BEDROOM 1	0009	7/10/2014	7/11/2014	144 in ²	<10 µg/ft ²
7/10 KL 10 Site: WINDOW WELL BEDROOM 1	0010	7/10/2014	7/11/2014	112 in ²	<13 µg/ft ²

M. Apfeldorfer
 Miron Apfeldorfer, Laboratory Manager
 or other approved signatory

Reporting limit is 10 µg/wipe. The QC data associated with these sample results included in this report meet the method quality control requirements, unless specifically indicated otherwise. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities.

* slight modifications to methods applied Samples received in good condition unless otherwise noted. Quality Control Data associated with this sample set is within acceptable limits, unless otherwise noted
 Samples analyzed by EMSL Analytical, Inc. New York, NY AIHA-LAP, LLC-ELLAP Accredited #102581, NYS ELAP 11508

Initial report from 07/14/2014 10:40:14

03



EMSL - MA 7 Constitution Way, Ste 107 Woburn, MA 01801 (781) 933-8411 (781) 933-8412 Fax	EMSL - CT 29 N. Plains Hwy, Unit 4 Wallingford, CT 06492 (203) 284-5948 (203) 284-5978 Fax	EMSL - NY 307 West 38 th Street New York, NY 10018 (866) 448-3675 (212) 290-0058 Fax	EMSL - NJ 107 Haddon Avenue Westmont, NJ 08108 (800) 220-3675 (856) 858-4960 Fax
---	---	--	---

Your Name: Brandy LeBlanc **Project Manager:**

Company: Eagle Environmental, Inc.

Street: 8 South Main Street, Suite 3

City/State/Zip: Terryville, CT 06786

Phone: 860-589-8257 ext. 203 **Fax:** 860-585-7034 **Email:** bleblanc@eagleenviro.com; nporter@eagleenviro.com; dwynne@eagleenviro.com; rsiotch@eagleenviro.com

Project Name: Capital Studio Architects - Environmental Review **Project #:** 14-028.12T17

Project Location: 2 Apple Tree Lane, Mystic **Project State (US):** CT

TURNAROUND TIME

3 Hours
 6 Hours
 24 Hours
 48 Hours
 72 Hours
 4 Days
 5 Days
 6-10 Days

SAMPLE MATRIX

Air
 Bulk
 Soil
 Wipe
 Micro-Vac
 Drinking Water
 Wastewater
 Chips
 Other

ASBESTOS ANALYSIS

- PCM - Air**
- NIOSH 7400 (A) Issue 2: August 1994
 - OSHA w/TWA
- TEM AIR**
- AHERA 40 CFR, Part 763 Subpart E
 - NIOSH 7402 Issue 2
 - EPA Level II
- PLM - Bulk**
- EPA 600/R-93/116
 - NY Stratified Point Count
 - California Air Resource Board (CARB) 435
 - NIOSH 9002
 - PLM NOB (Gravimetric) NYS 198.1
 - EPA Point Count (400 Points)
 - EPA Point Count (1,000 Points)
 - Standard Addition Point Count
- SOILS**
- EPA Protocol Qualitative
 - EPA Protocol Quantitative
 - EMSL MSD 9000 Method fibers/gram
 - Superfund EPA 540-R097-028 (dust generation)
- TEM BULK**
- Drop Mount (Qualitative)
 - Chatfield SOP-1988-02
 - TEM NOB (Gravimetric) NY 198.4
- TEM MICROVAC**
- ASTM D 5755-95 (Quantitative)
- TEM WIPE**
- ASTM D-6480-99
 - Qualitative
- TEM WATER**
- EPA 100.1
 - EPA 100.2
 - NYS 198.2
 - Other:

LEAD ANALYSIS

- Flame Atomic Absorption**
- Wipe, SW846-7420 ASTM non ASTM
 - Soil, SW846-7420
 - Air, NIOSH 7082
 - Chips, SW846-7420 or AOAC 5.009 (974.02)
 - Wastewater, SW 846-7420
 - TCLP LEAD SW846-1311/7420
- Graphite Furnace Atomic Absorption**
- Air, NIOSH 7105
 - Wastewater, SW846-7421
 - Soil, SW846-7421
 - Drinking Water, EPA 239.2
- ICP - Inductively Coupled Plasma**
- Wipe, SW846-6010 ASTM non ASTM
 - Soil, SW846-6010
 - Air, NIOSH 7300

MATERIALS ANALYSIS

- Full Particle Identification
- Optical Particle Identification
- Dust Miles and Insect Fragments
- Particle Size & Distribution
- Product Comparison
- Paint Characterization
- Failure Analysis
- Corrosion Analysis
- Glove Box Containment Study
- Petrographic Examination of Concrete
- Portland Cement in Workplace Atmospheres (OSHA ID-143)
- Man Made Vitreous Fibers - MMVF's
- Synthetic Fiber Identification
- Other:

MICROBIAL ANALYSIS

- Air Samples**
- Mold & Fungi by Air O Cell
 - Mold & Fungi by Agar Plate count & id
 - Bacterial Count and Gram Stain
 - Bacterial Count and Identification
- Water Samples**
- Total Coliforms, Fecal Coliforms
 - Escherichia Coli, Fecal Streptococcus
 - Legionella
 - Salmonella
 - Giardia and Cryptosporidium
- Wipe and Bulk Samples**
- Mold & Fungi - Direct Examination
 - Mold & Fungi - (Culture follow up to direct examination if necessary)
 - Mold & Fungi - Culture (Count & ID)
 - Mold & Fungi - Culture (Count only)
 - Bacterial Count & Gram Stain
 - Bacterial Count & Identification (3 most prominent types)
 - Other:

IAQ ANALYSIS

- Nuisance Dust (NIOSH 0500 & 0600)
- Airborne Dust (PM10, TSP)
- Silica Analysis by XRD Niosh 7500
- HVAC Efficiency
- Carbon Black
- Airborne Oil Mist
- Other:

Additional Information/Comments/Instructions: ****PLEASE STOP ON 1ST POSITIVE WITHIN SETS**

Client Sample # (S)	7/10 KL Soil 01	7/10 KL Soil 05	TOTAL SAMPLE #
Assigned:	Kristen Liljehult		5
	<i>[Signature]</i>	Date: 7/10/14	Time: PM
	<i>[Signature]</i>	Date: 7-10-14	Time: PM
	<i>[Signature]</i>	Date: 7-10-14	Time: PM
	<i>[Signature]</i>	Date: 7/10/14	Time: 10:27 PM

**EMSL Analytical, Inc.**

307 West 38th Street, New York, NY 10018
 Phone/Fax: (212) 290-0051 / (212) 290-0058
<http://www.EMSL.com> manhattanlab@emsl.com

EMSL Order: 031426771
 CustomerID: EEVM50
 CustomerPO:
 ProjectID:

Attn: **Eagle Environmental, Inc. - CT**
8 South Main Street
Suite 3
Terryville, CT 06786

Phone: (860) 589-8257
 Fax: (860) 585-7034
 Received: 07/11/14 10:27 AM
 Collected: 7/10/2014

Project: 14-028.12T17/ CAPITAL STUDIO ARCHITECTS - ENVIRONMENTAL REVIEW/ 2 APPLE TREE LANE, MYSTIC/ CT

Test Report: Lead in Soils by Flame AAS (SW 846 3050B/7000B)*

<i>Client Sample Description</i>	<i>Lab ID</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Lead Concentration</i>
7/10 KL SOIL 01 Site: VEGETABLE GARDEN Desc: A SIDE	0001	7/10/2014	7/12/2014	130 mg/Kg
7/10 KL SOIL 02 Site: BARE SOIL FROM DRIPLINE OUT TO FENCE Desc: C SIDE	0002	7/10/2014	7/12/2014	74 mg/Kg
7/10 KL SOIL 03 Site: DRIP LINE BY C/D Desc: D SIDE	0003	7/10/2014	7/12/2014	66 mg/Kg
7/10 KL SOIL 04 Site: BARE SOIL BED - DRIPLINE Desc: D SIDE	0004	7/10/2014	7/12/2014	47 mg/Kg
7/10 KL SOIL 05 Site: BARE SOIL - DRIPLINE BY A/D Desc: D SIDE	0005	7/10/2014	7/12/2014	45 mg/Kg

M. Apfeldorfer

Miron Apfeldorfer, Laboratory Manager
 or other approved signatory

*Analysis following Lead in Soil/Solids by EMSL SOP/Determination of Environmental Lead by FLAA. Reporting limit is 40 mg/kg based on the minimum sample weight per our SOP. Unless noted, results in this report are not blank corrected. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities. Samples received in good condition unless otherwise noted. Results reported based on dry weight. "<" (less than) result signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. The QC data associated with the sample results included in this report meet the recovery and precision requirements established by the AIHA-LAP, unless specifically indicated otherwise.

Samples analyzed by EMSL Analytical, Inc. New York, NY AIHA-LAP, LLC-ELLAP Accredited #102581, NYS ELAP 11506

Initial report from 07/12/2014 22:43:57

APPENDIX 6
RADON TESTING REPORTS

RADON TESTING NOT PERFORMED

The structure is proposed to be elevated with the lowest level of the building not in contact with the ground.

APPENDIX 7
MOLD INSPECTION FORMS



EAGLE Environmental, Inc.

MOLD MOISTURE READING FORM

Eagle Project No: 14-028, 12717 Date: 2-10-14 Inspector: Andrew Cenero
 Facility Address: 2 Apple tree Mystic

MOISTURE MODE						
ROOM	COMPONENT	SUBSTRATE	REL. SURFACE MOISTURE	DRY	AT RISK	WET
001	wall stud	wood	18.5		low risk	
	wall stud	wood	17.2		low risk	
	ceiling beam	wood	11.2	/		
	ceiling beam	wood	12.0	/		
	ceiling beam	wood	11.5	/		
002	ceiling	gypsum board	6.1	/		
	ceiling	gypsum board	6.3	/		
	wall stud	wood	19.7		low risk	
	wall stud	wood	19.1		low risk	
	ceiling beam	wood	14.2	/		
	wall panel	wood	4.8	/		
	wall panel	wood	11.8	/		
	door casing	wood	14.2	/		
	wall	sheetrock	14.4	/		
	ceiling deck	wood	4.6	/		
	stair tread	wood	100.9	/		

HYGROMETER MODE				
TIME	ROOM	% RELATIVE HUMIDITY	AIR TEMP.	DEW POINT TEMP.
12:05 PM	001	46.2	84.4 F	59.9
12:15 PM	002	60.4	84.2	60.6



MOLD OBSERVATION FORM

Eagle Project No: 14-028, 1217-14 Date: 7-10-14 Inspector: AC

Facility Address: 2 Apple Tree Music

Location	Observation	Sample Number
001	Wood ceiling beams appear dry and no visible mold spores. Wall studs look black in color, water damage evident.	
002	The gypsum board ceiling is observed to have minor water stains.	
	Wall studs show evidence of water intrusion, wood studs are black.	
	- Sheetrock walls show no signs of water damage or mold growth.	
	- wood panels show no signs of mold.	

APPENDIX 8

ABATEMENT AND CONSULTING COST ESTIMATE

HAZARDOUS MATERIALS ABATEMENT COST ESTIMATES
APPLICATION NO.2011
2 APPLE TREE LANE
WEST MYSTIC, CONNECTICUT

ASBESTOS ABATEMENT COST ESTIMATE

MATERIAL	QUANTITY	UNIT COST	TOTAL COST
ASBESTOS BREECHING REMOVAL	1	\$ 1,200.00 EA	\$ 1,200.00
SUBTOTAL			\$ 1,200.00
ASBESTOS ABATEMENT CONTINGENCY			\$ 120.00
ASBESTOS TOTAL			\$ 1,320.00

MICROBIAL CONTAMINATION REMEDIATION COST ESTIMATE

MATERIAL	QUANTITY	UNIT COST	TOTAL COST
MICROBIAL REMEDIATION CONTINGENCY	1	\$ 1,800.00 EACH	\$ 1,800.00
SUBTOTAL			\$ 1,800.00
MICROBIAL REMEDITION CONTINGENCY			\$ 180.00
MICROBIAL REMEDIATION TOTAL			\$ 1,980.00

HAZARDOUS MATERIALS ABATEMENT SUBTOTAL \$ **3,300.00**

HAZARDOUS MATERIALS CONSULTING COST ESTIMATE

CONSULTING COST	QUANTITY	UNIT COST	TOTAL COST
HAZARDOUS MATERIALS CONSULTING CONTIN.	1	\$1,200.00 EACH	\$ 1,200.00
SUBTOTAL			\$ 1,200.00
CONSULTING CONTINGENCY			\$ 120.00
CONSULTING TOTAL			\$ 1,320.00

GRAND TOTAL \$ **4,620.00**

APPENDIX 9
EAGLE ENVIRONMENTAL, INC. LICENSES
AND LABORATORY CERTIFICATES

STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH

PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT


THE INDIVIDUAL NAMED BELOW IS LICENSED
BY THIS DEPARTMENT AS A

LEAD CONSULTANT CONTRACTOR

EAGLE ENVIRONMENTAL INC.

LICENSE NO.
001723
CURRENT THROUGH
04/30/15
VALIDATION NO.
08-794089


SIGNATURE


COMMISSIONER

ENVIRONMENTAL TRAINING AND ASSESSMENT

Certificate of Completion Lead Inspector/Risk Assessor — Refresher

Awarded To

Kristen Liljehult
269 Baileyville Road
Middlefield, CT 06455

Has successfully completed, and passed an examination covering the contents of s EPA Model Eight (8) Hour Refresher Training Course for Lead Inspector/Risk Assessor and in accordance with the Department of Public Health Standards established pursuant to Section 20-477 of the Connecticut General Statutes. Approved under the New Standard and 40 CFR 745.225(c)(8)(i).


Course Date: 1/2/2014

Examination Date: 1/2/2014

Examination Grade: 88%

Certificate Number: LI/RAR-00350

Expiration Date: 1/2/2015



Stephen J. Craig, Training Manager

Boston Lead Company, LLC
dba

Environmental Training and Assessment
62 Washington Street
Middletown, CT 06457
860-347-7277

STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH
PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT
THE INDIVIDUAL NAMED BELOW IS CERTIFIED
BY THIS DEPARTMENT AS A
LEAD INSPECTOR/RISK ASSESSOR

KRISTEN P. LILJEHULT

CERTIFICATION NO.
002206
CURRENT THROUGH
12/31/14
VALIDATION NO.
03-715183

 SIGNATURE

 COMMISSIONER

Certificate of Training

Awarded to

ANDREW CARNEVALE

For successful completion of a 4 Hour, 1/2 Day
**Asbestos Building Inspector
Annual Refresher Training**
January 2, 2014

This training was approved and given in accordance with the
Regulations for Connecticut State Agencies
RCSA 20-440-19 and RCSA 20-441 and meets the
requirements of the TPA-Revised MAP under TSCA Title II of 4/4/94.

Presented by

Mystic Air Quality Consultants, Inc.


1204 North Road, Groton, CT 06340 (800) 247-7746


Certificate Number: ABIRF22726

Exam Grade: 100

Expiration Date: 01/02/2015

Exam Date: 01/02/2014



Christopher J. Eident, CIH, CSP, RS



George Williamson, Training Director
Richard Haffey, Training Director

STATE OF CONNECTICUT
DEPARTMENT OF PUBLIC HEALTH
PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT
THE INDIVIDUAL NAMED BELOW IS LICENSED
BY THIS DEPARTMENT AS A
ASBESTOS CONSULTANT INSPECTOR

ANDREW C. CARNEVALE

LICENSE NO.
000850
CURRENT THROUGH
10/31/14
VALIDATION NO.
03-702940


SIGNATURE


COMMISSIONER

State of Connecticut, Department of Public Health
Approved Environmental Laboratory

THIS IS TO CERTIFY THAT THE LABORATORY DESCRIBED BELOW HAS BEEN APPROVED BY THE STATE DEPARTMENT OF PUBLIC HEALTH PURSUANT TO APPLICABLE PROVISIONS OF THE PUBLIC HEALTH CODE AND GENERAL STATUTES OF CONNECTICUT, FOR MAKING THE EXAMINATIONS, DETERMINATIONS OR TESTS SPECIFIED BELOW WHICH HAVE BEEN AUTHORIZED IN WRITING BY THAT DEPARTMENT.

EMSL ANALYTICAL, INC. - MANHATTAN, NY

LOCATED AT 307 West 38th Street IN New York, NY 10018
AND REGISTERED IN THE NAME OF Peter Frasca, Ph.D.

THIS CERTIFICATE IS ISSUED IN THE NAME OF James Hall WHO HAS BEEN DESIGNATED
BY THE REGISTERED OWNER/AUTHORIZED AGENT TO BE IN CHARGE OF THE LABORATORY WORK COVERED BY THIS CERTIFICATE OF
APPROVAL AS FOLLOWS:

ASBESTOS

Examination For:

Bulk - Identification (PLM, TEM)

Air - Fiber Counting (PCM, TEM)

Water - TEM

SEE COMPLETE PRINT OUT FOR SPECIFIC TESTS APPROVED

Environmental Health & Housing

Examination For:

Lead in Paint

Lead Paint in Soil

Lead in Dust Wipes

THIS CERTIFICATE EXPIRES September 30, 2014 AND IS REVOCABLE FOR CAUSE BY THE STATE DEPARTMENT OF PUBLIC HEALTH
DATED AT HARTFORD, CONNECTICUT, THIS 4th DAY OF October, 2012



Registration No.

PH-0170

SUZANNE BLANCAFLOR, MS
CHIEF, ENVIRONMENTAL HEALTH SECTION