


SECOND FLOOR



EXTERIOR WORK NOTES

- 1 ROOFING WORK ACCORDING TO CONTRACT DOCUMENTS
- 2 GUTTER AND DRIP EDGE DAMAGE, REPAIR ACCORDING TO CONTRACT DOCUMENTS



PHOTO 4
(DAMAGED PORTION OF ROOF FACING FRONT OF HOUSE LEFT OF CHIMNEY TO BE REPAIRED) (N.T.S.)





PHOTO 5
(DAMAGED PORTION OF ROOF ABOVE SECOND FLOOR FACING REAR OF HOUSE TO BE REPLACED) (N.T.S.)



PHOTO 6
(DAMAGED PORTIONS OF ROOF ABOVE SECOND FLOOR FACING FRONT OF HOUSE TO BE REPLACED) (N.T.S.)

LEGEND

-  WOOD FLOOR, CEILING BOARD, & WALL BOARD
-  ROOF SLOPES TO BE REPAIRED OR REPLACED



1084 Cromwell Avenue, Suite A-2
Rocky Hill, CT 06067
Telephone: (860) 436-4364
Fax: (860) 436-4626
www.martinezcouch.com

**PROJECT 1533 - 2210 PARK AVENUE,
BRIDGEPORT, CONNECTICUT 06604**

NO.	DATE	REVISIONS	BY	CHK	APPV

DRAWN BY: MBR CHECKED BY: REC SCALE: 1"=4" DATE: 06/25/2014

**SCHEMATIC
ROOF LAYOUT**

JOB NO.	DRAWING NUMBER	SHEET
33-262-1533	BASEMAP 33-262-1533.dwg	A-2.0