

DEPARTMENT OF DEVELOPMENTAL SERVICES

North Region

Hardwood Refinishing Project

555 Pomfret Street Putnam, 505 Middle Turnpike, Storrs

85 Mountain Road, 87 Mountain Road, 242 Mountain Road Newington, 310 Beelzebub Road South Windsor

Project# DDS-2006

Questions and Clarifications and Addendums

General Questions & Answers:

Question: There is "sanitary molding" in place at several locations, how is this to be addressed?

Answer: This will be left in place and the floors finished up to them.

Question: To what extent are the moldings to be painted?

Answer: Any new 1/4 round or any molding nicked during the process shall be repainted as per the specifications.

Question: At one location there are a couple of broken stair treads, are these to be replaced?

Answer: Yes

505 Middle Turnpike;

Clarifications:

1. The stairs are removed from the project.

I want to thank all of you who asked questions and shared your expertise. JM