

Addendum #1 CORRECTION to BID Document 12/19/11

On Page 22

It says:

IB 1.05 Location and Examination of Site

1. The work will be performed at: 555 Pomfret Street Putnam, 505 Middle Turnpike, Storrs
85 Mountain Road, 87 Mountain Road, 242 Mountain Road Newington, 310 Beelzebub Road
South Windsor

Should Read

IB 1.05 Location and Examination of Site

1. The work will be performed at: 395 Church Street, Newington CT

Regards,

John Massicotte

Plant Facilities Engineer

Department of Developmental Services-North Region

155 Founders Plaza

255 Pitkin Street East Hartford, CT 06108

Office-860-263-2486, Fax- 860-622-4996